







APPENDIX A

Appendix A – OSI Photo Comparison

	Striking vehicle
Bryson	 <p>A photograph of a silver Ford pickup truck from a front-three-quarter view. The truck is parked on a gravel lot. The front end shows significant damage, including a crumpled hood and a bent metal bar attached to the bumper. A timestamp in the bottom right corner reads "03/24/2020 10:00".</p>
Mendoza	 <p>A photograph of a blue pickup truck from a front-three-quarter view. The truck is parked on a dirt road. It features a black bull bar over the front grille. The license plate is visible and reads "T3-F1F3".</p>
Bacho	 <p>A close-up photograph of the front end of a vehicle that has been involved in a collision. The front bumper and hood are severely damaged and crumpled. A yellow measuring tape is placed horizontally across the front of the vehicle to measure the extent of the damage.</p>

	Struck vehicle	
Bryson		
Mendoza		
Bacho		

	Occupant Intrusion	
Bryson	 A photograph of the interior of a vehicle, specifically the driver's side. A yellow outline is drawn around the back of the driver's seatback. A yellow double-headed arrow points to this outline. To the right of the outline, the text "OUTLINE OF BACK OF DRIVER SEATBACK" is written in yellow. A yellow bag is visible on the floor in the foreground.	
Mendoza	 A photograph of the interior of a red vehicle. The driver's side door is open, and the interior is heavily damaged. The driver's seat is visible, and there is significant debris and structural damage around it. The red exterior of the vehicle is visible on the right side of the frame.	
Bacho (2 nd row)	 A photograph of the interior of a vehicle, showing the second row. The seats are light-colored. There is significant damage and debris visible, particularly on the right side of the frame, indicating a severe impact or intrusion.	

